



Dynaudio Sub 6

Release notes

Skanderborg – February 7th, 2025

DYNAUDIO

Dynaudio A/S
Sverigesvej 15
DK-8660 Skanderborg
T: +45 8652 3411
dynaudio.com

Changes in FW 06.0002

Fixes a bug that may result in too low output when using the Preset filter for Confidence 20/30/50/60 speakers

Note: After updating to this version, we strongly recommend re-calibrating the volume setting of the subwoofer, if using the Preset filter for Confidence 20/30/50/60.

Other preset filters and manual filters are not changed, and do not require re-calibration.